

How to Test your Mag-Touch Baton.

Place the front copper touch point onto an I.D. Point and watch to see if the RED L.E.D. Comes on

Trouble Shooting

<u>Problem</u>	<u>Cause</u>	<u>Solution</u>
<u>Baton</u>		
Not Clocking	>Loose Wire	>Contact YOUR Distributor
	>Faulty Electronics	>Contact YOUR Distributor
	>Faulty I.D. Point	>Point needs to be replaced
	>I.D.Point: Wet or Dirty	>Clean I.D.Point with dry clean cloth
Light stay's flashing	>Loose Wire	>Contact YOUR Distributor
Light doesn't come on	>Loose Wire	>Contact YOUR Distributor
	>L.E.D. Stopped working	>Contact YOUR Distributor
	>Battery Flat	>Contact YOUR Distributor
	>Unit has been Tampered with	>Contact YOUR Distributor
Not giving Correct Date (eg: 2008/00/00 or Year -2)	>Computer Software is out dated	>Download the LATEST Version
	>Time Crystal Faulty	>Contact YOUR Distributor
	>Computer Software is out dated	>Download the LATEST Version
(eg: 25:00 or 00:00:00)	>Time Crystal Faulty	>Contact YOUR Distributor
<u>Computer</u>		
Checking Port Num	>U.S.B cable inserted into new Port	>Refer to File "Setting Port Number"
	>Computer Has been Upgraded	>Refer to File "Setting Port Number"
	>new installation clashing	>Refer to File "Setting Port Number"
	with Mag-Touch software	
	>Program Opened Twice	Close Programs and Open ONLY 1(One)
Baton Time Wrong	>Baton Time is set from Computer	>Check and set Computer Time & Date
<u>Docking Station</u>		
No Light/s	>Not Plugged in	>Unit is not properly inserted
	>Loose Wire	>Contact YOUR Distributor